DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-012653 Address: 333 Burma Road **Date Inspected:** 06-Mar-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Li Yang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No **Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

TRIAL ASSEMBLY YARD

MAGNETIC PARTICLE INSPECTION

OBG 6CW

PUNCH LIST ITEM #442

This Q.A Inspector performed Magnetic particle Inspection of approximately 15% of the area previously tested and accepted by ZPMC Quality control personnel. This QA Inspector generated a (M.T) report for this date. The members are identified as the OBG segment 6West Designation are as follows.

LD005-004-007

ULTRASONIC INSPECTION

OBG 6CW PUNCH LIST ITEM #442



WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This Q.A Inspector performed Ultrasonic Inspection of approximately 10% of the area previously tested and accepted by ZPMC Quality control personnel. This QA Inspector generated a (U.T) report for this date. The members are identified as the OBG segment 6West Designation are as follows.

LD005-004-007

This QA Inspector randomly observed the following work in progress.

OBG SEGMENT 6WEST

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 054467 performing Shielded Metal Arc Welding process for weld CA013-002 located on PCMK weld between side panel and edge panel counter weight side. ZPMC QC Mr. Zhong Yang Gang monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-354-SMAW-2G (2F)-FCM-Repair-1. Weld repair report identified as B-WR10749.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 037743 performing Shielded Metal Arc Welding process for weld CA029-005 located on PCMK weld between side panel and edge panel counter weight side. ZPMC QC Mr. Zhong Yang Gang monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-354-SMAW-2G (2F)-FCM-Repair-1. Weld repair report identified as B-WR10753.

This Quality Assurance (QA) Inspector observed ZPMC NDT Inspector performing Ultrasonic Inspection on the weld between deck plate I rib to edge panel at FL003 location near the panel point 38.

Unless otherwise noted, all work observed on this dated appeared to generally comply with applicable contract documents.





Summary of Conversations:

No relevant conversations.

Comments

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Utekar,Shrikant	Quality Assurance Inspector
Reviewed By:	Dawson,Paul	QA Reviewer